



THE ALL
INCLUSIVE
PORT

Safety information

for visitors to the City Port



Contact Main gate

If questions call+46 (0)155 25 81 00

Emergency only

Call our internal emergency number
.....+46 (0)155 25 82 99
or+46 (0)70 640 97 00

If internal emergency contact point can't be reached, call 112 and follow their instructions.

State: Your name. Where the accident occurred.
What kind of accident. Number of injured persons.

Rescue: If possible – give first aid. Assess the situation and act without risk of your own safety in all forms of emergency response.



Port of Oxelösund – City Port

- 1 Main entrance/gate* & Control centre for dry bulk
- 2 Stuvaregården
- 3 Head office Port of Oxelösund
- 4 Swecem AB
- 5 C14 Bio-oil
- 6 Thomas Cement AB
- 7 Bitumen terminal
- 8 Turning area
- 9 Svenska Foder AB
- 10 Terminal office
- 11 Workshop - Vehicles
- 12 RoRo-terminal
- 13 Workshop - Mechanical and Electrical
- 14 Stevedoring office
- 15 Oil terminal
- 16 Maritime Administration Sjöfartsverket

Warehouses Bulk storage

- M3 Warehouse 3
- M4 Warehouse 4

Warehouses ISPS area

- M2 Warehouse 2
- M2A Warehouse 2A
- M7 Warehouse 7

Warehouse & storage areas H, I, L, M, N

- M1 Warehouse 1
- M5 Warehouse 5
- M6 Warehouse 6
- M8 Warehouse 8
- M9 Warehouse 9
- NB: Nordic Bulkers - warehouse

♥ = Emergency defibrillator (an additional defibrillator is located in the production leader's vehicle)

— = Gates

Skeppargatan	ISPS area
Bulk storage (dry bulk)	Oil terminal
Warehouse & storage areas H, I, L, M, N	

*Gate B, C, E are alternative gates, which our gate staff might require you to use for entrance or departure. Otherwise use main gate.

Keep yourself updated

There are areas with different safety rules. Our gate or contact person informs you of which areas you may visit and the rules that applies. Do not hesitate to ask our staff about e.g. the traffic situation and where to park, even if your contact person is not a port employee.

Pay attention to what is going on around you. Depending on type of goods handled, there can be risks such as dusting, sudden noise, intense traffic and hanging goods. In warehouses and other confined spaces there can be toxic gases. Follow signs.

It is prohibited to visit the conveyor facility or warehouses unless approved by our contact person. Visitors can borrow helmets and safety vests.

Information for ships

It is prohibited to walk by foot in the quay area. For transportation between ship – main gate – ship the following applies:

Contact Port Guides

Phone.....+46 (0)73 079 52 90
Email.....ledsagare@oxhamn.se
Mo – fr: 06:30-08:30, 09:00-12:00, 12:30-15:30
(not on weekends nor public holidays)

Times as per below please contact

Taxi Nyköping-Oxelösund

Booking (two hours notice).....+46 (0)155 21 75 00
Mention "Shuttle service Port of Oxelösund", the port, quay number, name of your ship.
Mo – fr: 17:00-18:00 (not on public holidays)
Weekends & public holidays: 12:30-14:30, 16:30-18:30

SSG On site

The app SSG On site shows e.g. contacts at the site, internal emergency number, safety information and map with overview of the area.



**Download SSG On site from
App Store or Google Play**

Signs must be respected

Below are some examples of signs that often occurs within the port. Pay attention and follow the signs.

Please note that signs can change from time to time, e.g. depending on type of goods stored in our warehouses.



In all production areas.



Along Skeppargatan.



Helmet and safety vest/clothing are required in all production areas. Visitors can borrow.



Warning light on vehicle is required in all production areas.



Gas detector is required in many warehouses, the conveyor facility, confined spaces and in the cavern of the oil terminal.



Respiratory protection and/or protective eyewear are required e.g. in some warehouses depending on type of goods stored.

Areas

Skeppargatan

Along this road, Skeppargatan, you find the head office of Port of Oxelösund, several tenants and the storage areas L and M. It is outside the ISPS area and with several parking possibilities. The speed limit is 30 km/h. Heavy vehicles share the road with regular traffic. Drive carefully and follow signs and rules. For rules for storage areas L and M, see purple area.

Oil terminal

Just outside the port you find the oil terminal. Our staff on site informs you of the special rules of the oil cavern, which is a Seveso facility. Wear helmet, safety vest/clothing and gas detector when visiting the cavern. Below ground level there is no net coverage for cell phones or two-way-radios. EX-zones exist due to risks for toxic and explosive gases. Follow signs and the directions of our staff.

Warehouse & storage areas H, I, L, M, N

On storage areas H, I, L, M, N and within the warehouse area with warehouses 1, 5, 6, 8, 9, including also Nordic Bulk activity, there are at times a high level of activity. Observe caution! At the gate they can give advice on the best route. On vehicles, warning lights are required. When meeting heavy vehicles make eye contact. Outside vehicles helmet and safety vest/clothing are required.

It is prohibited to enter warehouses unless approved by our contact person. Gas detector is often required due to e.g. risk of toxic gases. Depending on type of goods risks vary and respiratory protection and protective eyewear are also often required. Follow signs!

Bulk storage (dry bulk)

The area has no defined roads and there are activities around the clock. At times traffic situation is intense and the area should be avoided if possible. Pay attention and follow signs and instructions from our staff. Do not stay close to piles of material due to risk of collapse. At the gate they are well aware of the ongoing activities and can give advice on the best route. Same rules are valid for the storage at Stegeludden.

On vehicles, warning lights are required. When meeting heavy vehicles make eye contact. Outside vehicles, helmet and safety vest/clothing are required.

ISPS area

This area has no defined roads. It consists of our terminal area, storage areas F, Inner F and G, quays with cargo handling, warehouses 2, 2A, 7 and rail traffic. Do not park on or close to train or crane rails. At times traffic situation is intense and the area should be avoided if possible. Pay attention and follow signs and the gate or port staff's instructions. At the gate they can give advice on the best route.

On vehicles, warning lights are required. When meeting heavy vehicles make eye contact. On the quays and outside vehicles helmet and safety vest/clothing are required. When working on the quay life vest is required.

It is prohibited to enter warehouses unless approved by our contact person. Depending on type of goods risks vary and e.g. gas detectors, respiratory protection and protective eyewear might be required. Follow signs!

